

RFI #002:

No.1 Only one tree needs protection and is located on far edge of site. See prior questions and answers for these questions.

No. 2 (RE: requirement to submit for schedule of values)

Yes.

No. 3 will bid due date change.

No, bid due date remains the same.

No. 4 (RE: requirement for schedule of values)

Yes.

No. 5 will the city amend completion date.

See prior questions and answers.

No. 6 (Re: percentage for bid bond).

The correct amount of bid security required is five percent (5%) as set forth in Section 0200, subsection 6.0 entitled "BID SECURITY (BID BOND)".

No. 6 a. (Re: percentage for bid bond)

The relevant portion of Section 0100 is hereby revised as follows: Bid Security in the amount of five percent (5%) of the Total Base Bid must accompany the Bid in accordance with the Instructions to Bidders.

No. 6 b. (Re: percentage for bid bond)

This reference is correct. Bid Security in the amount of five percent (5%) of the Total Base Bid must accompany the Bid in accordance with the Instructions to Bidders.

No. 6 C. (Re: percentage for bid bond)

Section 401 (Bid Bond Form) is hereby revised to reflect that Bid Security in the amount of five percent (5%) of the Total Base Bid must accompany the Bid in accordance with the Instructions to Bidders:

**1. KNOW ALL PERSONS that we, _____ as
Principal, and _____ as Surety,
are held and firmly bound unto the City of Key Colony Beach, Florida (hereafter called the
("Owner")) in the penal sum of _____ dollars (\$.00), (five percent (5%) of the
Total Base Bid) as hereinafter set forth and for the payment of which sum well and truly to be
made we bind ourselves, our executors, administrators, successors and assigns, jointly and
severally, by these presents;**

RFI#003

No. 1 Can precast piles be substituted for auger cast piles?

No substitutions.

No. 2 Tree disposition plan how are tree protection being addressed?

See prior questions and answers.

No.3 provide an asbestos and lead survey for existing structures.

Asbestos will be abated prior to site turn over to selected vendor.

No lead paint survey done.

No.4 Plans show no dumpster area.

That is correct.